

ID Number MDLTNPS 06 Facility ADMINISTRATION AND HIGH SCHOOL ALP (2ND)

1. RELOCATE THE SIGNS TO THE PROPER LOCATION WHICH IS ON THE "LATCH SIDE OF THE DOOR" MOUNTED 60" FROM FLOOR TO THE CENTER OF THE SIGN.

Rest Rooms? Yes

Open Meeting Interior Route? Yes

Meeting Room? Yes **Location**

Voting Space Location

Parking Voting? Yes

Public Address System? Yes

Assistive Listening System? Yes

Eating Facility? Yes

Rooms? Yes

Special Features? Yes **Location**

Standard Used ADAAG

Notes: ****GENERAL NOTE FOR "ALL SCHOOLS"**

PROBLEMS:

1. DOORS LEADING INTO AREAS OF DANGER *ie.* ELECTRICAL CLOSETS, BOILER ROOMS, JANITORIAL CLOSETS OR ANY OTHER ROOMS THAT PERSONS WITH DISABILITIES CAN GET HURT.

POSSIBLE SOLUTIONS:

1. PROVIDE PROPER TACTILE WARNING STRIPS ON ALL DOOR KNOBS/LEVERS LEADING INTO THESE AREAS OF DANGER ALSO AS REQUIRED UNDER THE CODE "ALL DOORS LEADING INTO AREAS OF DANGER MUST AND WILL BE LOCKED AT ALL TIMES".

****GENERAL NOTE FOR "ALL SCHOOLS" WITH STAIRS/STAIRWELLS:**

PROBLEMS:

1. THE STAIRWELL HANDRAILS DO NOT EXTEND THE REQUIRED 12" PARALELL TO THE FLOOR AT THE TOP AND BOTTOM OF STAIR LANDINGS.

POSSIBLE SOLUTIONS:

1. HAVE EXTENTIONS WELDED AT THE TOP AND BOTTOM OF THE STAIR LANDINGS AS

**ID Number MDLTNPS 06 Facility ADMINISTRATION AND HIGH SCHOOL ALP (2ND
REQUIRED BY THE CODE.**

"THROUGH OUT SCHOOL"

PROBLEM:

1. NO LEVER TYPE HARDWARE PROVIDED.

POSSIBLE SOLUTION:

1. INSTALL PROPER LEVER TYPE HARDWARE ON DOORS LEADING INTO CLASSROOM AND OFFICE AREAS AND ANY OTHER DOOR THAT STUDENTS, GENERAL PUBLIC OR TEACHERS USE.

The Governor's Commission on the Handicapped provides Technical Assistance (Informal Guidance to assist in understanding the ADA and other Federal and State Disability Laws and Regulations to individuals and entities). This is Technical Assistance, not Legal Advice as to your Rights and Responsibilities under the Law.